



2005



2006

Aerial photographs of the southwest side of Cedar Lake taken in 2005 and 2006

On the 2006 photograph on the right, the outlined area shows the extent of clear cutting that occurred at the wetland along the north side of Kings Corner Road. The land cover change (from forested to open field) is an example of how development activities can impact the hydrology of this area, and ultimately Cedar Lake.



KIESER & ASSOCIATES
ENVIRONMENTAL SCIENCE & ENGINEERING